

Sanitary Sewer Overflow 5-Day Follow Up Report

Report Submitted By		
Date:	6/23/2015	
Facility name:	Gary L. Kron WRF	
Ohio NPDES permit no.:	3PK00033*MD	
Period covered by report:	6/23/2015	
Contact person		
Name:	Michael McGlothin	
Title:	Superintendent	
Mailing address:	8471 Lakeshore Blvd. Mentor, Ohio 44060	
County:	Lake	
Telephone:	(440)350 - 3431	
Email:	Michael.mcglothin@lakecountyohio.gov	
Signature required at end of form		
Overflow Information		
Event start date and time – if multiple locations, include information for each	6/23/2015 7:00am	
Event end date and time	6/23/2015 9:00am	
Location(s) the SSO — include unique ID number of one exists	Prouty Lift Station Concord, Ohio 44077	
Destination(s) of overflow	☐ Basement or building ☐ Ground ☐ Storm sewer to receiving water ☒ Directly to receiving water	
Estimated volume (million gallons) - if multiple locations, include volume for each	.115	
Sewer system component(s) from which release occurred	☐ Manhole ☐ Constructed overflow ☐ Pipe crack ☒ Pump station ☐ Other (explain)	
Cause(s) of overflow	Extreme weather	



Sanitary Sewer Overflow 5-Day Follow Up Report

	!	
Report Submitted By		
Date:	6/23/2015	
Facility name:	Gary L. Kron WRF	
Ohio NPDES permit no.:	3PK00033*MD	
Period covered by report:	6/23/2015	
Contact person		
Name:	Michael McGlothin	
Title:	Superintendent	
Mailing address:	8471 Lakeshore Blvd. Mentor, Ohio 44060	
County:	Lake	
Telephone:	(440)350 - 3431	
Email:	Michael.mcglothin@lakecountyohio.gov	
Signature required at end of	form	
Overflow Information		
Event start date and time – if multiple locations, include information for each	6/23/2015 6:45am	
Event end date and time	6/23/2015 9:15am	
Location(s) the SSO — include unique ID number of one exists	Manhole on Madison Ave. Painesville Twp.,Ohio 44077	
Destination(s) of overflow	☐ Basement or building ☐ Ground ☐ Storm sewer to receiving water ☐ Directly to receiving water	
Estimated volume (million gallons) - if multiple locations, include volume for each	.003	
Sewer system component(s) from which release occurred	☑ Manhole ☐ Constructed overflow ☐ Pipe crack ☐ Pump station ☐ Other (explain)	
Cause(s) of overflow	Extreme weather	



Sanitary Sewer Overflow 5-Day Follow Up Report

Report Submitted By		
Date:	6/23/2015	
Facility name:	Gary L. Kron WRF	
Ohio NPDES permit no.:	3PK00033*MD	
Period covered by report:	6/23/2015	
Contact person		
Name:	Michael McGlothin	
Title:	Superintendent	
Mailing address:	8471 Lakeshore Blvd. Mentor, Ohio 44060	
County:	Lake	
Telephone:	(440)350 - 3431	
Email:	Michael.mcglothin@lakecountyohio.gov	
Signature required at end of	form	
Overflow Information		
Event start date and time – if multiple locations, include information for each	6/23/2015 5:30am	
Event end date and time	6/23/2015 9:30am	
Location(s) the SSO — include unique ID number of one exists	Manholes on Water Street in Fairport Hbr., Ohio 44077	
Destination(s) of overflow	☐ Basement or building ☐ Ground ☐ Storm sewer to receiving water ☐ Directly to receiving water	
Estimated volume (million gallons) - if multiple locations, include volume for each	.007	
Sewer system component(s) from which release occurred	Manhole	
Cause(s) of overflow	Extreme weather	



Sanitary Sewer Overflow 5-Day Follow Up Report

Report Submitted By		
Date:	6/23/2015	
Facility name:	Gary L. Kron WRF	
Ohio NPDES permit no.:	3PK00033*MD	
Period covered by report:	6/23/2015	
Contact person		
Name:	Michael McGlothin	
Title:	Superintendent	
Mailing address:	8471 Lakeshore Blvd. Mentor, Ohio 44060	
County:	Lake	
Telephone:	(440)350 - 3431	
Email:	Michael.mcglothin@lakecountyohio.gov	
Signature required at end of form		
Overflow Information		
Event start date and time – if multiple locations, include information for each	6/23/2015 5:30am	
Event end date and time	6/23/2015 8:30am	
Location(s) the SSO — include unique ID number of one exists	Twilight Lift Station Mentor, Ohio	
Destination(s) of overflow	☐ Basement or building ☐ Ground ☐ Storm sewer to receiving water ☒ Directly to receiving water	
Estimated volume (million gallons) - if multiple locations, include volume for each	.001	
Sewer system component(s) from which release occurred	☐ Manhole ☐ Constructed overflow ☐ Pipe crack ☐ Pump station ☐ Other (explain) Lift Station Vault	
Cause(s) of overflow	Extreme weather	